

# UNITED STATES ENVIRONMENTAL PROTECTION AGEN

SDMS Document ID

999 18<sup>th</sup> STREET - SUITE 300 DENVER, CO 80202-2466 http://www.epa.gov/region08

January 26, 2006

Mr./Ms. Jan Buckstein (Real Teeth Llc) 1660 S Albion St. #718 Denver, CO 80222

Dear Mr./Ms. Jan Buckstein (Real Teeth Llc),

This letter certifies that soils on the property at 3739 Marion Street in Denver, Colorado, have been remediated in accordance with the U.S. Environmental Protection Agency's (EPA) Record of Decision for the Vasquez Boulevard and Interstate 70 Superfund Site (VB/I-70), Operable Unit 1, signed by EPA on September 25, 2003. The required work was accomplished in accordance with EPA approved work plans. The remediation successfully addressed the health risks associated with exposure to arsenic and lead in soils at this property.

The clean-up action conducted by the EPA and the U.S. Army Corps of Engineers (USACE) addressed residences where the soil concentrations of lead and/or arsenic exceeded the action levels of 400 parts per million (ppm) and/or 70 ppm, respectively. The clean up consisted of excavation of the top 12 inches of soil at the listed property. The excavated area was replaced with clean soils.

In order to assure that your property remains protected from lead contamination, it may be necessary to maintain the exterior of your home to prevent any chipping or peeling paint from being deposited in your yard. Very old paint (from 1978 or before) could contain lead contaminates. An EPA representative will be contacting you to schedule a lead based paint assessment of the exterior of your home. EPA will provide for the initial abatement of lead based paint if necessary.

If you require more specific information concerning the clean-up of your property, please contact me at U.S. EPA (8EPR-SR), 999 18<sup>th</sup> Street, Suite 300, Denver, CO 80202-2466, Attn: Victor Ketellapper, or 303-312-6578, or Pat Courtney at 303-312-6631.

Sincerely,

Victor Ketellapper

Project Manager



### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8
999 18<sup>th</sup> STREET - SUITE 300
DENVER, CO 80202-2466
http://www.epa.gov/region08

26 de Enero de 2006

Señor /Señora Jan Buckstein (Real Teeth Llc) 1660 S Albion St. #718 Denver, CO 80222

Estimado(a) Señor/Señora Jan Buckstein (Real Teeth Llc),

Este carta certifica que tierra en el propiedad 3739 Marion Street en Denver Colorado, ha sido remediado de acuerdo con la U.S. Environmental Protection Agency's (EPA) Recuerdo de Decisión para el Vasquez Boulevard y Interstate 70 Superfund Site (VB/I-70), Operable Unit 1, Firmado por EPA en September 25, 2003. El trabajo requerido era realizado de acuerdo con EPA confirmado plan del trabajo. La remediación eliminado con éxito los riesgos asociados con la exposición a arsénico y plomo en la tierra en su propiedad.

La acción de limpieza conductazo por EPA y el U.S. Army Corps of Engineers (USACE) dirigido a residentes donde las concentraciones de plomo y/o arsénico en la tierra excedido el nivel de acción de 400 partes por millón (ppm) y/o 70 ppm respectivamente. La limpieza consistido de la excavación de la primera doce pulgadas de tierra de la propiedad listado. El área excavado era reemplazado con tierras limpias.

Para asegurar que su propiedad permanece protegido de la contaminación de plomo, podría ser necesario a mantener el exterior de su hogar a prevenir cualquier astilla o la pintura a se descascara y deposita en su propiedad. Pintura muy viejo (de 1978 o antes) podría contener contaminantes de plomo. Un representante de EPA les contactará a hacer una reunión para una evaluación de pintura con plomo para la exterior de su hogar. EPA provendrá la primera rebaja de pintura basado con plomo si sea necesario.

Si quisiera mas información especifica en relación de la limpieza de su propiedad, por favor contáctame en U.S. EPA (8EPR-SR), 999 18<sup>th</sup> Street, Suite 300, Denver, CO 80202-2466, Attn: Victor Ketellapper, or 303-312-6578, or Pat Courtney at 303-312-6631.

Sinceramente,

Victor Ketellapper Gerente del Proyecto

#### **Consent For Access To Property**

#### RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name:  JAN BUCKSTEIN		Phone:	303-550-7215
	Address: 3739 MARION	N ST	
Addresses of Properties covered by this	Address:		
Agreement:	Address:		

#### PURPOSE OF RESPONSE ACTIVITIES

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed. The Grantor will have an opportunity to review and approve the planned soil removal and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

#### ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:

- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses,
   etc:
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

### AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact the VB/I-70 Command Center at (303) 487-0377.

I grant access to my propertie	s	I do not grant acc	cess to my properties
Jany Er	- 09-25-0	5	
Signature	Date	Signature	Date
☐ I would like to be present o		ing that is required. n that will need to be replac	ed.



# UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

999 18<sup>th</sup> STREET, SUITE 300 DENVER, CO 80202-2466 Phone 800-227-8917 http://www.epa.gov/region08

Ref: 8EPR-SR

September 21, 2005

JAN BUCKSTEIN 1660 S ALBION ST #718 DENVER, CO 80222

**RE: 3739 MARION ST** 

Dear JAN:

The United States Environmental Protection Agency (EPA) has tested your property for arsenic and lead soil contamination as pert of the Vasquez Boulevard/Interstate 70 (VB/I-70) Superfund Site. Concentrations of Arsenic and/or lead found in your soil are high enough for your property to qualify for the removal action EPA is performing this year.

ADDRESS	EPA Cleanup Leve			
Lead				
550 parts per million (ppm)	above 400 ppm			
Arsenic				
16 ppm	above 70 ppm			

EPA would like to remove the top layer of soil from your yard and replace it with clean soil. EPA will then re-landscape your yard to a condition similar to original. All work will be performed by EPA for free. EPA requires your consent to proceed as soon as possible. An Access Agreement that will allow the EPA to perform the soil removal work accompanies this letter. I strongly encourage you to sign this agreement and mail it back to the following address:

US EPA – VB/I-70 Project Site Attention: Victor Ketellapper 10 East 55<sup>th</sup> Avenue Denver, Colorado 80216

Your property will be scheduled for soil removal provided we promptly receive the signed Access Agreement with a telephone number where you can be contacted. EPA will coordinate the soil removal activity with you to reduce any inconvenience to you. Upon completion of the cleanup, EPA will issue a letter stating that your property has been cleaned and that no further action is necessary.

Once the attached access agreement has been received, representatives of EPA will contact you to discuss the removal of contaminated soil from your property. In the meantime, if you have further questions regarding the removal of contaminated soil at your property, please contact us at (303) 487-0377.

Sincerely

Victor Ketellapper

Remedial Project Manager

United States Environmental Protection Agency (US EPA)

RMATION		DECISION CRITERIA			
6828 3739		Target Property?  Soil Sampled?  Removal Required?			
MARION ST 3739 MARION ST	Find Record	Removal Complete?			
80205	<b>5</b>	Phase Arsenic Decision Value			
ATION		Lead Decision Value			
JAN BUCKSTEIN 1660 S ALBION ST #718					
DENVER, CO 80222		OTHER SAMPLE RESULTS  Media Description  Arsenic  Lead			
	6828 3739  MARION ST 3739 MARION ST  80205  ATION  JAN BUCKSTEIN 1660 S ALBION ST #718	ATION  JAN BUCKSTEIN  1660 S ALBION ST #718			

•

.....

,



Date last updated: Wednesday, October 12, 2005

### **3** Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

View Map/Historic District Listing for this Property
Link to property tax information for this property
Link to property sales information for this neighborhood
Link to property sales information for all Denver neighborhoods

#### PROPERTY INFORMATION

Property Type: Commercial Parcel: 0227129028000

Name and Address Information Legal Description

REAL TEETH LLC L 25 TO 27 INC BLK 1 HYDE

1660 S ALBION ST #718 PARK ADD

DENVER, CO 80222 RESIDENTIAL 4 THRU 8 UNITS

Property Address: Tax District

3739 MARION ST -3747 DENV

#### **Assessment Information**

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	32800	2610		
Improvements	294200	23420		
Total	327000	26030	0	26030
Prior Year				
Land	32800	2610		
Improvements	304800	24260		
Total	337600	26870	0	26870

Style: Other Reception No.: 2004253916

Year Built: 1905 Recording Date: 12/14/04
Building Sqr. Foot: 2,984 Document Type: Quit Claim

Bedrooms: Sale Price: 10

Baths Full/Half: 0/0 Mill Levy: 64.402

Basement/Finished: 0/0

Lot Size: 9,530 Zoning: B4 This spreadsheet performs screening level calculations to estimate the effect of peeling leaded paint on the average concentration of lead in yard soil 3739 Marion Street

INPUTS	Variable	Units	House
General	Mixing depth in yard	cm	2.54
	Mixing depth in yard	inches	1
	Soil density	g/cm3	2.5
	RBC in soil	mg/kg	400
	Bkg in clean fill	mg/kg	50
	-		Small
House-specific	Area of the exposure unit	m2	136.0101
	Area of the exposure unit	ft2	1464
	Concentration of lead in paint	mg/cm2	31.2
	Area of peeling paint	m2	7.525146
	Area of peeling paint	ft2	81
COMPUTATIONS	<b>S</b>		
	Mass of lead from paint	mg	2.3E+06
	Volume of soil	cm3	3.5E+06
	Mass of soil	kg	8.6E+03
	Incremental concentration	mg/kg	271.8
	Maximum acceptable area of p	• •	9.7
	Maximum acceptable area of p		104.2
DECISION			ОК

## **Lead Based Paint Qualification Calculations**

Property ID	Positive XRF Readings	SF of Peeling Paint	Comments
6828	1238	2	
6828	1240	2	
6828	1241	12	
6828	1242	0.5	Highest XRF Reading Detected 31.2
6828	1243	1	
6828	1244	12	
6828	1245	0.5	
6828	1246	1	
6828	1247	12	
6828	1248	0.5	
6828	1249	1	
6828	1250	12	
6828	1251	0.5	
6828	1252	1	
6828	1253	12	
6828	1254	0.5	
6828	1261	0.75	
6828	1263	0.83	
6828	1264	0.83	
6828	1266	4	
6828	1268	1.25	
6828	1269	1.25	
6828	1273	0.83	
			· · · · · · · · · · · · · · · · · · ·

House Total SF of Peeling Paint Garage Total SF of Peeling Paint

80.24



## Daily Quality Control Report VB/I-70 Lead Based Paint Assessment

Date: 06-26-06

Property Location 3739 mario 7

Type ar	nd Location of	Tests Perf	ormed and	Results					
Property ID	XRF Reading #	Lead POS.	Result NEG.	Direction	Location of Result	Condition	Square Feet	Substrate	Color
6828		1.0			CHI BANTON	Intact Cracked Chipped Peeling			
	/236	1.0			Culi bour ion	Intact Cracked Chipped Peeling			
	/237	1.1	_		Colisentia	Intact Cracked Chipped Peeling			
	1238	26.2		SE	window Framp	Intact Cracked Chinge Peeling	121x2"	wase	note
	12-39		0.4	SW SF	window Framp	Intact Cracked Chipped Peeling		wood	91880
	1240	6.9		5.F	Window Frame	Intact Cracked Chipped Peeling	12'xz"	-00d	91997
	1241	3.5		£ast	soffit above 3739		3' x 4'	لهمول	44.46
	1242	31.2		East	transom window	Intact Cracked Chipped Peeling	3' x 2"	wood	green
	1243	2.7	_	East	3741 window Frame	Intact Cracked Chipped Peeling	6'x 2"	wood	9 reen
	1244	3.6		East	Suffit above 3741	Intact Cracked Chipped Peeling	3'x4'	wood	White
	1245	15.8		East	transom window frame	Intact Cracked Chipped Peeling	3' X 2"	wood	grees
	1246	1.9		East	3743 vindou frame	Chippe Peeling	6' x Z"	wood	green
	1247	25.3		East	3743 soff, + above	Intact Cracked	3'x 4'	wood	White
	1248	17.1		East	transom window frame		3'x 2"	000d	91881
	1249	2.0		East	3745 Window frame	Intact Cracked Chipped Peeling	61×2"	wood	green
	1250	26. Z		East	3745 soffix above	Intact Cracked Chipped Ceeling	3'24'	mood	White
	1251	24.6		East	3745 Transon window frame	Intact Cracked Chipped Peeling	ろ'x Z"	<del>  /</del>	91081
/ <i>V</i>	1252	20.8		E954	3747 wildow frame	Intact Cracked Chipped Peeling	6' X Z "	m000	dieg)

I certify that the above report is complete and correct and that I, or my authorized representative, have inspected all work performed this day and have determined that all materials, equipment, and workmanship are in strict compliance with the plans and specifications, except where noted herein.

ontractor's Quality Control Representative	<u>,                                     </u>
--	---



## Daily Quality Control Report VB/I-70

Date: of Shot

Lead Based Paint Assessment

Property Location 3739 marion St

Type and	Location	of Tests	<b>Performed</b>	and Results
I y pc anu	LUCAUVII	OI I COLO	I CI IOI IIICG	WITH TECOMICS

	1 ype ai	ia Location of	rests Peri	огшец апс						
	Property ID	XRF Reading	Lead POS.	Result NEG.	Direction	Location of Result	Condition	Square Feet	Substrate	Color
6828		1253	30.6	NLO.	East	3747 soffit alone	Intact Cracked Chipped Peeling	3'x4'	W-00	White
		1254	28.3		Ear4	3747 transom window srame	Initation Cracked	31x2"	Wood	91881
		1255		50.02	East	3747 fence +	Intact Cracked Chipped Peeling		mass	pink
		1256		0.27	EKT	corrice moding	Chipped Peeling		was	grav
		1257	·	0.30	W	3739 window frame		<b>.</b>	wood	tan
		1260		0.01	w.	3739 window 5111	Intact Cracked Chipped Peeling		Sour	tan
		1261	1.9		727	Window frame on addon	Intact Cracked Chipped Peeling	3'x3"	wood	+057
		1262	4.4		W	3739 sid/ng-addon	Chipped Peeling		کے موں در	tan
		1263	3.7		W	3739 window frame	Intact Cracked Chipped Ceeling	5'x 2."	wood	tan
		1264	1.7		ω	3741 Window frame	Intact Cracked Chipped Peeling	5' X Z"	wood	197
		1265	2.4		~	3741 addon siding	Intact Cracked Chipped Peeling	i	mood	ta^
		1266	8.5		J	3741 exterior door	Intact Cracked Chipped Petting	2'x2'	Mady	MURIOR
		1267		0.01	W	3741 add on windowsill			Mood	tan
		1268	1.8		w_	3743 add on Window from		5'x3"	wood	tar
		1269	1.8		W	3743 window frame	Intact Cracked Chipped Peeling	5'x2"	wood	Tan
		1270		0.4	<u> ~ </u>	3745 add on Siding	Intact Cracked Chipped Peeling		mode	tan
		1271		0.5	<u> </u>	3745 add -on window frame			uood	tan
	<u>/'\/</u>	1272		0.8	W	3745 window frame	Intact Cracked Chippe Peeling		1900	Tan

I certify that the above report is complete and correct and that I, or my authorized representative, have inspected all work performed this day and have determined that all materials, equipment, and workmanship are in strict compliance with the plans and specifications, except where noted herein.

Contractor's Quality Control Representative	
---	--




## Daily Quality Control Report **VB/I-70** Lead Based Paint Assessment


Date: 6/26/06


Property Location 3739 Marion S+
Type and Location of Tests Performed and Results

Type ar	nd Location of	Tests Peri	ormed and	<u> Results                                   </u>					
Property ID	XRF Reading #	Lead POS.	Result NEG.	Direction	Location of Result	Condition	Square Feet	Substrate	Color
			NEG.			Intact Cracked	<u></u>	1	
6828	1273	3.0		7	317 / window trame	Chipped Peeling	5'XZ"	nasq	Yellow
	1274		0.9	W	3747 add-on siding is	Intact Cracked Chipped Peeling		4000	797
1	1275		0.6	7	3747 window frame 3747 add-on siding of 3747 window frame	Intact Cracked Chipped Peeling		mood	tan
						Intact Cracked	–		
	<del></del>					Chipped Peeling		<del></del>	
			:			Intact Cracked Chipped Peeling			
						Intact Cracked		<del> </del>	
						Chipped Peeling			[
						Intact Cracked			
						Chipped Peeling			ļ .
<del></del>					· ·	Intact Cracked			$\vdash$
İ						Chipped Peeling			
						Intact Cracked			
		I				Chipped Peeling			
						Intact Cracked	·	·	
						Chipped Peeling			
						Intact Cracked	<del></del>		
						Chipped Peeling			
						Intact Cracked			
					<u> </u>	Chipped Peeling		1	
						Intact Cracked			
					\	Chipped Peeling			j l
						Intact Cracked			
						Chipped Peeling		_	<u>1</u> 1
						Intact Cracked			
						Chipped Peeling			
						Intact Cracked			
					`	Chipped Peeling			
						Intact Cracked			
						Chipped Peeling		ļ	
						Intact Cracked	<u> </u>		
						Chipped Peeling			

I certify that the above report is complete and correct and that I, or my authorized representative, have inspected all work performed this day and have determined that all materials, equipment, and workmanship are in strict compliance with the plans and specifications, except where noted herein.







Total = 3837

pragrave! 10x /2 = 140 24224=576 2×10 = 20 4×14 = 54 3x42=126 27×73=1971 10x2=20 6×43 = 258 5x14 = 70 2931 4/x/4=56 4x14 =54 2 x10 = 20 2476=152 5x14 = 70 10x2 = 20

4x 13 = 52 13x4=50 5x14 = 10

982=18 382=6 2814=28 Ce// 303550-2015

JAN B. BUCKSTEIN

Di Duploutts 303.564.9288

Condominium / Management 1660 South Albion St. #718 Denver, CO 80222 (303) 757-7759

3637

## Meagan Redfern

From:

OCARS\_Pro@uncc.org

Sent:

Tuesday, October 25, 2005 10:00 AM

To:

Meagan Redfern

Subject:

UNCC EMLCFM 2005/10/25 #00134 A0411535-00A NORM NEW

EMLCFM 00134 UNCCa 10/25/05 09:59 AM A0411535-00A NORM NEW STRT LREQ

Ticket Nbr: A0411535-00A

Original Call Date: 10/25/05 Time: 09:59 AM Op: MRE

Locate By Date : 10/27/05 Time: 11:59 PM Meet: N Extended job: N

State: CO County: DENVER City: DENVER

Addr: 3739 Street: MARION ST

Grids: 03S068W26NW : : Legal: C

Lat/Long: 39.769198/-104.978289 39.769198/-104.968859

: 39.761889/-104.978289 39.761889/-104.968859

Type of Work: SOIL EXCAVATION Exp.: N

Boring: N

Location: \*LOCATE ENTIRE LOT \*ACCESS OPEN\*TO INCLUDE ALL EASEMENTS TO

CITY

: PROPERTY. INDIVIDUAL STRUCTURE. PROPERTY IS A 5 - PLEX, ALSO

TO

: INCLUDE ADDRESS, NUMBERS 3741,3743,3745 AND 3747.

Company : PROJECT RESOURCES INC. Type: OTHR

Caller: MEAGAN REDFERN Phone: (303)487-0377
Alt Cont: AMY JAMES Phone: (303)487-0377

Fax: Email: MREDFERN@PROJECTRESOURCESINC.COM

Done for: CORPS OF ENGINEERS/EPA

Remarks:

Members 360NT3 = 360 NETWORK-TOUCH AMERICA 360NT4 = 360 NETWORK-TOUCH

AMERICA

Members ADSTA1 = ADESTA COMM ATCT01 = AT&T

Members CMSND00= COMCAST - NORTH DENVER DNSCH1 = DENVER PUBLIC

SCHOOLS

Members ICGTL3 = ICG TELECOMMUNICATIONS LVL311 = LEVEL 3

COMMUNICATIONS

Members MCI01 = MCI PCKVEL = XCEL ENERGY-ELEC

TRANSM

Members PCNDU0 = XCEL ENERGY-NORTH DENVER PSND14 = XCEL ENGY--APPT

SCHEDULE

Members QLNCND0= QWEST LOCAL NETWORK QLNCND1= QWEST LOCAL

NETWORK

Members SPRN01 = U.S. SPRINT TWTEL1 = TIME WARNER

TELECOM

Members WCG01 = WILTEL COMMUNICATION

You are responsible for contacting any other utilities that are not

listed above

including the following tier 2 members not notified by the center:

DNVH20 DENVER WATER DEPT (303)628-6666
DNVPR1 DENVER PARKS & REC. (303)458-4839
DTEO01 DNVR TRAFFIC ENG OPERAT. (720)865-4001
WWMG01 WASTEWATER MGMT DIVISION (303)446-3744

3741 - relderly lady needs Ramp.

mait man - Sam (clean-out)

ell - (720)298-9558

DC +

55E & 949

ges) hexhe

bsov





## **Property Check-List**

### Yes/No

- 1. Sprinkler System?
- 2. \_ N Basement Photos?
- 3. Photos of Water Meter?
- 4. All 3 Signatures?
- 5. Number of Trees?
- 6. Approximate Voucher Size?
- 7. Are all trees and bushes clearly labeled on the map?
- 8. A Clotheslines marked and is it removed or replaced?
- 9. House accessible for equipment?
- 10. Owner clear of everything they will need to remove?
- 11. Owner clear the dates when we call him are approximate?
- 12. A second walk through done on the property to double check the map by the individual who did the video/photos?







# **Property Access Checklist**

Property ID: 10828		□ WORK STARTED ON:/_/     □ WORK COMPELTED ON:/_/_			
Property Address: 3739 MAK	210N	☐ WORK	COMPELTED	ON:/_/	
·					
Property Owner: JAN BUCKS	tein	Property Renter:			
Mailing Address: 3739 MARIC	W L	Home Phone:			
		Fax:			
TV Di		Cell/Pager:			
Home Phone: 3/550 - 2215 Fax:		Additional Information:			
Cell/Pager:					
- Comit agon					
Notification Letter	Sent:/		By:		
Access Agreement	Signed:		By:		
Restoration Agreement			By:		
Topsoil Sampling (if applicable)	Signed://		By:		
☐ Disposal Sampling (if applicable)			By:		
Garden Sampling (if applicable)			By:		
Utility Clearance	Called:/				
☐ Video/Photos (Before)	<del>                                     </del>			R. Karin	
☐ Video/Photos (During)			By:		
☐ Video/Photos (After)	On:/ By:		Ву:		
☐ Video/Photos (30-Day)	On:/_	/ By:			
☐ Property Completion Agreement	Signed:/	/ / By:			
Final Report	Issued://		By:		
Air Monitoring (as applicable)					
Community Crew On:// By:					
Results:					
Community Crew On:	//_	By:			
Results:					
	//	By:			
Results:					



Property ID:

Item:

**Property Address:** 

## **Restoration Agreement**

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Owner: Jan Burrstan
Phone:
•
on the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all know tilities, subsurface features, surface structures and landscaping features, access location(s) to be used be ontractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photo y referencing the photo-log number with an arrow indicating direction of view.
Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)
The removal, storage, disposal, and/or return of these items is the Owner's responsibility.
item:
Swings +, Chairs trash, carnet any



Item:

# Items To Be Removed By Contractor During Remediation And <u>Not Replaced</u> (Use additional sheets as necessary)

Item:	l ·
item:	
Item:	·
Item:	
Item:	
Item:	
ı	tems To Be Removed By Contractor During Remediation And <u>Replaced</u> (Use additional sheets as necessary)
item:	any Lencer, for access
item:	any Jenner for arress
	any Jenner for mess
Item:	any Jenner for moress
Item:	any fencer for novem
Item: Item:	any Jenner for mess







# Landscape Inventory (Use additional sheets as necessary)

Item	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	3831	Square Feet	
Number of trees > 2 inch trunk diameter	5		
Number of trees < 2 inch trunk diameter			
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc.  Attach a sketch of the sprinkler layout.	N/A		Zones:
Number of and total size of all gardens / flower beds.  Attach a sketch of relative	# Of Beds:  # Of Gardens:	·	Ft <sup>2</sup> Of Beds:
sizes and locations.			Ft <sup>2</sup> Of Gardens:





## Project Resources Inc.

ltem	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials not to be replaced by contractor.  Note this value will be used to issue a plant voucher to the property owner.	Total # Of Beds:	\$	Total Ft <sup>2</sup> Of Beds To Be Replaced With Certificate:
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed.  Include a sketch of were each plant will be placed by the contractor.		Each	Only Use For Plants That Are Being Saved and Replanted
Agreed upon area of property to be replaced with grass sod.  Include a sketch of the area(s) to be replaced with grass sod.	NJA	SF	Total Ft <sup>2</sup> Of Sod To Be Laid:
Area of City or County property to be landscaped per their requirements.  Include a sketch of the area (s)	Total Fr <sup>2</sup> :	SF	Sod:  Brown Mulch:  Red Mulch:
Agreed upon area of property to be replaced with mulch.	Total Ft <sup>2</sup> Of Mulch:	SF	Red: 9016  Brown:



Additional Comments / Inst	ructions Continued:	
:		
		·
	•	ļ
	•	
<del></del>		
Check the box if Owner does not want PRI to doc	ument interior foundatio	n walls and possible
pre-existing damage. By checking this box PRI is n interior of house, including foundation cracks or fissure	ot responsible for any ( 98.	Jamage done to the
agree   I do not agree	1 agree	☐ I do not agree
	Cn > - 1	0 (10-1-
Owner's Signature Date	Contractor's Signature	Uston (0/19/05) Date
Jan Prignavale Control of the Contro	John J. S.	
$oldsymbol{arphi}$		

froject Besnotten lac

## **Property Completion Agreement**

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

Property ID: 6828	7
Property Address: 4739 - 3747	7
Owner: Au Buchatin	7
Phone: (LU. 3)660-2215	7
Restoration Items in Question:	_
Maric	7
Nam;	1
Meson;	]
lines:	]
Autr:	]
Ana;	]
Need to Restread the Need to Restread the Fence between ## 3739 g  Fence between # 175 / pg.ng over  3741 marion. H's / pg.ng over  Previally.	
I agree restoration is completed, except as mated  I do bet agree restoration is enumbered.	
I digree that the sprinklin spring is weating property	
Ithe 124/05 magain Rechard	"/ 28/c
Paristr's Streeture Units Contractor's Streeture Units	<del>-</del> /03

## **TARGET SHEET**

# EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1035188

SITE NAME:	VASQUEZ BOULEVARD AND I-70
DOCUMENT DATE:	01/26/2006
Due to one of the fo	DOCUMENT NOT SCANNED ollowing reasons:
☐ PHOTOGRAPHS	
3-DIMENSIONAL	-
□ OVERSIZED	
☑ AUDIO/VISUAL	
☐ PERMANENTLY	BOUND DOCUMENTS
☐ POOR LEGIBILIT	ГҮ
☐ OTHER	
☐ NOT AVAILABLE	<b>Ξ</b>
	JMENTS NOT TO BE SCANNED , Data Validation, Sampling Data, CBI, Chain of Custody)
DOCUMENT DESCR	RIPTION:
3 - DVDs OF PRO	OPERTY VIDEO, PROPERTY #6828